

TUNDRA  
DRONE

# SOOT LIGHT 5

Instruction Manual



**SOOT LIGHT 5**



Parts included in BOX

## SOOT LIGHT 5

### STEP: 1

- Align the control unit with the mounting holes on the drone's top, as shown in the image.



### STEP: 2

- Use the mounting screws to attach the control unit to the drone as shown in the image.





## SOOT LIGHT 5



### STEP: 3

- Confirm if both the Mounting screws are tight.



### STEP: 4

- Align and fit the Light unit to the drone Camera by pushing down the locking detail towards the camera as shown in the image.



- Align the ribs of the Camera to the slots in the Light unit as shown in the image.




- Make sure the Light unit is fitted and aligned correctly to the drone camera as shown in the image.

## SOOT LIGHT 5



### STEP: 7

- Attach the Wire holder 1 to the Gimbal arm as shown in the picture.



- Make sure the wires are routed through both the pockets on the Wire holder 1




## SOOT LIGHT 5

### STEP: 8

- Attach the Wire holder 2 to the Gimbal arm as shown in the image.



- Make sure the wires are routed through both the pockets on the Wire holder 2 as shown in the image.



## SOOT LIGHT 5



### STEP: 9

- Plug PSDK cable to USB port in the Drone as shown in the image.

